


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: Joao Carlos Widar

GRE/Prodemge: João Antinossi Responsável/cliente: José dos Santos Saraiva

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet 2MBPS **VSAT** SEE-ICAS-22128



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

: Forward link up : 65281, Prodemge@Vodanet Network

Frequency Frequency : 12.176222 GHz Symbol Rate : 4.882980 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

: On Pilot Frame length : Short : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                   : 14.5 dB
Input Power
                 : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -16.1 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Es/No
                    : 12.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -188 us (281813 us)
Frequency correction: 20 Hz
# device snow
System Information:
    Name : SEE-ICAS-22128
: ICARAÍ DE MINAS
# device show
                        : ICARAÍ DE MINAS - MG
   Contact
                       :
   System Up time : 0 days, 01:06:21
CPU Load : 18%
System time(UTC) : 25 October 2017 23:34:48
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
   Main board ID : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:48:98
Satellite (DVB) : 00:20:0e:10:48:98
Transec not Supported by this device !
# arp show
                State MacAddr
  10.212.181.2 Dynamic 54:04:a6:8e:d3:f6 1
Pinging 10.212.181.1 with 32 bytes of data:
Reply from 10.212.181.1: bytes=32 time=592ms TTL=56
Reply from 10.212.181.1: bytes=32 time=568ms TTL=56
Reply from 10.212.181.1: bytes=32 time=608ms TTL=56
Reply from 10.212.181.1: bytes=32 time=574ms TTL=56
Reply from 10.212.181.1: bytes=32 time=610ms TTL=56
Reply from 10.212.181.1: bytes=32 time=577ms TTL=56
Reply from 10.212.181.1: bytes=32 time=579ms TTL=56
Reply from 10.212.181.1: bytes=32 time=556ms TTL=56
Reply from 10.212.181.1: bytes=32 time=555ms TTL=56
Reply from 10.212.181.1: bytes=32 time=558ms TTL=56
```

```
Ping statistics for 10.212.181.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 555ms, Maximum = 610ms, Average = 577ms
Lista de sites acessados:
www.globo.com - ok
www.yahoo.com - ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok
Responsável pelo teste de navegação:
Nome: José dos Santos Saraiva
Função: Diretora
Identidade: Masp-602487.1
```