


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Jean Polini

Responsável/cliente: Luiz Cesar Sousa Pinto **GRE/Prodemge:** João Antinossi

> Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-PIIS-22201 2048/1024 **VSAT**



Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

Frequency : 12.176419 GHz Symbol Rate : 4.883011 Msps Frequency

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Shown DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
 _____
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -20.7 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -473 us (281885 us)
Frequency correction: 50 Hz
System Information:
   Name
                        : SEE-PIIS-22201
    Location
                        : PINT POLIS - MG
    Contact
   System Up time : 0 days, 00:21:38

CPU Load : 31%

System time(UTC) : 04 November 2017 12:59:39
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
                       : 120026 R6.2
    Main board ID
    MAC addresses:
Pinging 10.213.0.1 with 32 bytes of data:
Reply from 10.213.0.1: bytes=32 time=609ms TTL=56
Reply from 10.213.0.1: bytes=32 time=585ms TTL=56
Reply from 10.213.0.1: bytes=32 time=733ms TTL=56
Reply from 10.213.0.1: bytes=32 time=557ms TTL=56
Reply from 10.213.0.1: bytes=32 time=552ms TTL=56
Reply from 10.213.0.1: bytes=32 time=574ms TTL=56
Reply from 10.213.0.1: bytes=32 time=562ms TTL=56
Reply from 10.213.0.1: bytes=32 time=553ms TTL=56
Reply from 10.213.0.1: bytes=32 time=558ms TTL=56
Reply from 10.213.0.1: bytes=32 time=575ms TTL=56
Ping statistics for 10.213.0.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 552ms, Maximum = 733ms, Average = 585ms
NetAddr
         State MacAddr
     10.213.0.2 Dynamic 64:1c:67:62:2e:12 1
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com – ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Luiz Cesar Sousa Pinto Função: Diretor Telefone: 38 999467960 MASP: 831873-5 Horário de Funcionamento: 07:00 as 18:00