

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

Responsável/cliente: ANA CELIA SOARES DA SILVA GRE/Prodemge: João Antinossi

VILELA

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-GOES-22802 **VSAT** 2Mbps



Satellite (DVB) RX Configuration ______

Auto start . Enable:
Max Traffic MODCOD : 23 16APSK-9/10
PV watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

symbol Rate : 4.883027 : 52 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB

```
Input Power
                    : -35 dBm
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power
                  : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -12.6 dBm
ODU Output Power : 33.9 dBm
EIRP
                    : 47.2 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -144 us (281092 us)
Frequency correction: 30 Hz
System Information:
   Name
                        : SEE-GOES-22802
    Location
                        : GOVERNADOR VALADARES
    Contact
    System Up time : 0 days, 02:00:49 CPU Load : 15%
    System time (UTC) : 17 November 2017 22:06:24
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4f:93
Satellite (DVB) : 00:20:0e:10:4f:93
NetAddr
             State MacAddr
   10.214.216.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.214.216.1 with 32 bytes of data:
Reply from 10.214.216.1: bytes=32 time=532ms TTL=56
Reply from 10.214.216.1: bytes=32 time=573ms TTL=56
Reply from 10.214.216.1: bytes=32 time=538ms TTL=56
Reply from 10.214.216.1: bytes=32 time=725ms TTL=56
Reply from 10.214.216.1: bytes=32 time=544ms TTL=56
Reply from 10.214.216.1: bytes=32 time=566ms TTL=56
Reply from 10.214.216.1: bytes=32 time=553ms TTL=56
Reply from 10.214.216.1: bytes=32 time=544ms TTL=56
Reply from 10.214.216.1: bytes=32 time=542ms TTL=56
Reply from 10.214.216.1: bytes=32 time=537ms TTL=56
Ping statistics for 10.214.216.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 532ms, Maximum = 725ms, Average = 565ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok

www.educacao.mg.gov.br – ok

www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: ANA CELIA SOARES DA SILVA VILELA

Função: Diretora MASP: 992070-3

Telefone: 33- 3284-7025

Funcionamento: 07:00 as 18:00