

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente Cristiano Veloso

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SACO-222052MbpsVSAT

Port Eth0 (SEE-SACO-22205-10.213.14.1)



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176715 GHz Symbol Rate : 4.882921 Msps S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 **SNR** : 16.5 dB Input Power : -32 dBm

dvb tx show

Satellite (DVB) TX Configuration

_____ : Enabled Auto start IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

: 46.5 dBW **EIRP**

Default CW Frequency: 0.000000 GHz

: VC-Mux ATM mode Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

: On (DVB-RCS2) State IDU Output Power : -19.7 dBm ODU Output Power : 33.4 dBm

EIRP : 46.7 dBW Es/No : 14.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -433 us (281544 us)

Frequency correction: 90 Hz

arp show

State MacAddr NetAddr 10.213.4.2 Dynamic 1c:39:47:5b:e2:48 1

device show

System Information:

Name : SEE-SACO-22205 Location : So Francisco - MG

Contact

System Up time : 0 days, 00:17:10

: 16% CPU Load

System time(UTC) : 01 November 2017 13:04:03

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4c:91 Satellite (DVB) : 00:20:0e:10:4c:91

#

Pinging 10.213.4.1 with 32 bytes of data:

Reply from 10.213.4.1: bytes=32 time=571ms TTL=56 Reply from 10.213.4.1: bytes=32 time=576ms TTL=56 Reply from 10.213.4.1: bytes=32 time=529ms TTL=56 Reply from 10.213.4.1: bytes=32 time=592ms TTL=56 Reply from 10.213.4.1: bytes=32 time=589ms TTL=56 Reply from 10.213.4.1: bytes=32 time=589ms TTL=56 Reply from 10.213.4.1: bytes=32 time=580ms TTL=56 Reply from 10.213.4.1: bytes=32 time=581ms TTL=56 Reply from 10.213.4.1: bytes=32 time=596ms TTL=56 Reply from 10.213.4.1: bytes=32 time=596ms TTL=56 Reply from 10.213.4.1: bytes=32 time=551ms TTL=56

Ping statistics for 10.213.4.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 502ms, Maximum = 596ms, Average = 536ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Cristiano Veloso
Identidade/Masp	Vice - diretor
Cargo	1268407-2
Telefone	038-9-9910-3383
Funcionamento	07:00 até 22:30