


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Santos Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Edsonina Gomes

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet 2048/1024 SEE-MAAS-22534 **VSAT**



dvb rx show

Satellite (DVB) RX Configuration ______ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status ______

: On Rx State

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176273 GHz

Symbol Rate : 4.883033 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 16APSK-5/6 - current max : 21

Pilot : On Frame length : Shor : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB ___: -35 dBm Input Power

```
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power
                 : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.1 dBm
ODU Output Power : 34.5 dBm
EIRP
                    : 47.8 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -386 us (280701 us)
Frequency correction: 60 Hz
# device show
System Information:
   Name
                       : SEE-MAAS-22534
    Location
                        : MAMONAS - MG
    Contact
   System Up time : 0 days, 00:47:23 CPU Load : 9%
    System time(UTC) : 12 November 2017 13:05:08
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.1
    MAC addresses:
   Ethernet (LAN)
 Transec not Supported by this device !
# arp show
                State MacAddr
   10.213.117.2 Pending 00:00:00:00:00:00 1
   10.213.117.3 Dynamic b8:ae:ed:8b:f4:bc 1
Pinging 10.213.117.1 with 32 bytes of data:
Reply from 10.213.117.1: bytes=32 time=559ms TTL=56
Reply from 10.213.117.1: bytes=32 time=576ms TTL=56
Reply from 10.213.117.1: bytes=32 time=590ms TTL=56
Reply from 10.213.117.1: bytes=32 time=562ms TTL=56
Reply from 10.213.117.1: bytes=32 time=645ms TTL=56
Reply from 10.213.117.1: bytes=32 time=571ms TTL=56
Reply from 10.213.117.1: bytes=32 time=582ms TTL=56
Reply from 10.213.117.1: bytes=32 time=519ms TTL=56
Reply from 10.213.117.1: bytes=32 time=619ms TTL=56
Reply from 10.213.117.1: bytes=32 time=544ms TTL=56
Ping statistics for 10.213.117.1:
```

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
Minimum = 519ms, Maximum = 645ms, Average = 576ms

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

Responsável pelo teste de navegação: João Gustavo

Nome: Edsonina Gomes Cardoso

Função: Diretora MASP: 325940-5

Telefone: 038 99119-4079