

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Joao Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Vivaldo Rodrigues Lima

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-SATO-231342MbpsVSAT

Port eth 0 SEE-SATO-23134(10.214.53.1)



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

NA State . OII

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176313 GHz Symbol Rate : 4.882905 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
                    : 15.3 dB
SNR
Input Power
                    : -40 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -20.0 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -303 us (279983 us)
Frequency correction: -30 Hz
# arp show
  NetAddr
                State MacAddr
                                            Ιf
   10.214.53.2 Dynamic b4:99:ba:00:92:6b 1
# device show
System Information:
   Name
                       : SEE-SATO-23134
    Location
                        : SANTO ANT NIO DO JACINTO - MG
    Contact
   System Up time : 0 days, 00:02:31 CPU Load : 15%
    System time (UTC) : 08 December 2017 10:30:39
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:51
Satellite (DVB) : 00:20:0e:10:5b:51
   Ethernet (LAN)
Pinging 10.214.53.1 with 32 bytes of data:
Reply from 10.214.53.1: bytes=32 time=534ms TTL=56
Reply from 10.214.53.1: bytes=32 time=582ms TTL=56
Reply from 10.214.53.1: bytes=32 time=528ms TTL=56
Reply from 10.214.53.1: bytes=32 time=571ms TTL=56
Reply from 10.214.53.1: bytes=32 time=564ms TTL=56
Reply from 10.214.53.1: bytes=32 time=548ms TTL=56
Reply from 10.214.53.1: bytes=32 time=559ms TTL=56
Reply from 10.214.53.1: bytes=32 time=580ms TTL=56
Reply from 10.214.53.1: bytes=32 time=541ms TTL=56
Reply from 10.214.53.1: bytes=32 time=559ms TTL=56
Ping statistics for 10.214.53.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 528ms, Maximum = 582ms, Average = 556ms
```

Resp: Vivaldo Rodrigues Lima Cargo:Diretor Masp:635823-8 Telefone:033-9-9931-5374 Funcionamento:07:00-22:00 Onde ficou: Em um computador da diretoria Sites acessados $\underline{\texttt{www.globo.co}} \texttt{m}$ www.google.com www.hotmail.com www.yahoo.com www.prodemge.gov.br www.educacao.mg.gov.br