

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Edison Lima Martins

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-NORO-22942 2Mbps





## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

## Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 05201, 111 : 12.176405 GHz : 4.883025 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.3 dB : -31 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -15.6 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -792 us (281378 us)
Frequency correction: 160 Hz
System Information:
                    : SEE-NORO-22942
    Name
    Location
                        : NOVO CRUZEIRO - MG
    Contact
    System Up time : 0 days, 00:45:39 CPU Load : 17%
    System time(UTC) : 22 November 2017 16:20:17
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:38
Satellite (DVB) : 00:20:0e:10:5b:38
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.215.135.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.215.135.1 with 32 bytes of data:
Reply from 10.215.135.1: bytes=32 time=551ms TTL=56
Reply from 10.215.135.1: bytes=32 time=547ms TTL=56
Reply from 10.215.135.1: bytes=32 time=592ms TTL=56
Reply from 10.215.135.1: bytes=32 time=533ms TTL=56
Reply from 10.215.135.1: bytes=32 time=531ms TTL=56
Reply from 10.215.135.1: bytes=32 time=539ms TTL=56
Reply from 10.215.135.1: bytes=32 time=543ms TTL=56
Reply from 10.215.135.1: bytes=32 time=583ms TTL=56
Reply from 10.215.135.1: bytes=32 time=545ms TTL=56
Reply from 10.215.135.1: bytes=32 time=537ms TTL=56
Ping statistics for 10.215.135.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 531ms, Maximum = 592ms, Average = 550ms
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Edison Lima Martins Função: Secretario MASP: 961839-8 Telefone: 33-98827-2303 Funcionamento: 07:00h às 21:30h