

WORK ORDER WO-7788

Equipment: P-205B centrifugal feed pump

Date: 2026-06-18

Reported by: Technician Rohan Mehta

Symptom: mechanical seal failure with cavitation causing a pressure drop during startup.

Action: replaced mechanical seal MS-4400 and completed lockout before service, per SOP-MAINT-051 Rev.2.

Inspection: the pressure-relief valve was tested; the quarterly relief valve test was completed under PM-2205.

The vibration trend was reviewed for two weeks and logged under PM-2205.

Compliance: rotating-equipment maintenance was recorded against the OISD-154 inspection cadence.

Follow-up: monitor the seal condition and vibration trend; refer to the OEM manual for the service interval.