

INSPECTION REPORT - Compressor K-330

Date: 2026-06-22

Inspector: Inspector Sanjay Kulkarni

Equipment: K-330 reciprocating compressor

Regulatory basis: PESO pressure-system licensing.

Findings: high vibration and bearing failure detected on the drive end, with overheating on the discharge.

Bearing SKF-6320 was replaced and the alignment corrected per PM-2205.

The current operating license is on file. The hydrostatic pressure test certificate is on file under PM-2205.

Note: only two of the three required quarterly relief valve tests were completed this year, a partial gap against the OISD-154 inspection cadence.

Recommendation: schedule the outstanding quarterly test and continue vibration trend monitoring.