

INCIDENT REPORT INC-2026-050

Date: 2026-06-25

Reporting supervisor: Supervisor Priya Nair

Summary: Pump P-205B experienced a pressure drop from mechanical seal failure, reducing feed to Compressor K-330, which then tripped on high vibration and overheating.

Contributing factors: seal failure on P-205B, cooling water strainer fouling, and a prior bearing failure on K-330.

Immediate action: isolated P-205B, replaced the mechanical seal MS-4400, and inspected the K-330 bearing SKF-6320 per PM-2205.

Regulatory references: OISD-154 rotating-equipment maintenance and PESO pressure-system licensing.

Lessons learned: correlate seal failure and vibration trends across coupled equipment; a single pump seal failure can cascade to a compressor trip.

Add a cross-system vibration trend review to the PM schedule.