





1	2	3	4	5	6
A					A
B					B
C					C
D					D
1	2	3	4	5	6

Sheet: /Manual Control/ File: manualctrl.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3	Id: 5/10	

DNP – test signal integrity without the active pullups and populate them if necessary



Sheet: /I2C Active Pullup1/
File: i2c.kicad_sch

Title:

Size: A4


Date:

KiCad E.D.A. 10.0.3

Rev:

Id: 6/10

DNP – test signal integrity without the active pullups and populate them if necessary



Sheet: /I2C Active Pullup2/
File: i2c.kicad_sch

Title:

Size: A4


Date:

KiCad E.D.A. 10.0.3

Rev:

Id: 7/10

DNP – test signal integrity without the active pullups and populate them if necessary



Sheet: /I2C Active Pullup/
File: i2c.kicad_sch

Title:


Size: A4

Date:

KiCad E.D.A. 10.0.3

Rev:

Id: 9/10



Sheet: /Syringe Pump/
File: syrpump.kicad_sch

Title:

Size: A4


Date:

KiCad E.D.A. 10.0.3


Rev:

Id: 10/10

Level shift the calibration signal from 3.3V to 5V



Level shift the bubble detection signal from 5V to 3.3V



Sheet: /Bubble Sensors/
File: bubblesensors.kicad_sch

Title:

Size: A4

Date:


Rev:

KiCad E.D.A. 10.0.3

Id: 12/10

Pressure sensors connect over SPI and have unique chip select pins

Address translator for fourth flow sensor – DNP if using only three
If the translator is not populated, connect the solder jumpers to use 4th connector



Sheet: /Sensors/
File: sensors.kicad_sch

Title:

Size: A4
KiCad E.D.A. 10.0.3

Date:

Rev:

Id: 13/10