

After moving an NIR calibration:

1 Do not reuse the old uncertainty formula

2 Take standards from many batches

3 Re-fit the transfer leaving one out

4 Report the resulting 90% interval

5 Watch for drift (Q residual)