

Blackreef — AxiomIQ Fleet Overview

Generated: 2026-03-07 23:39
Coverage: 2026-01-01 -> 2026-01-30 | Samples: 14400 | Engines: 4

Run Configuration
Version: 0.1.3

Key Changes Since Last Report

- No material fleet changes detected since last report.



Fleet Verdict

DG1, DG2, DG3 shows degradation and should be scheduled for inspection. DG4 remains healthy.

This page ranks generator sets by operational priority using health score, drift severity, and estimated time-to-limit.

Top Alerts

DG1 [MED] Health 62.3 | HTCW Outlet Temp | ETA N/A | Sched next maint
DG2 [MED] Health 62.3 | HTCW Outlet Temp | ETA N/A | Sched next maint
DG3 [MED] Health 63.0 | HTCW Outlet Temp | ETA N/A | Sched next maint

Engine	Trend	Health	Top Risk	Reason	Action	ETA	Pri
DG1		62.3	HT Cooling Water Outlet Temperature	Health 62.3 (<80) and ETA unavailable; schedule inspection (htcw_engine_outlet_temp_c).	Sched next maint	N/A	MED
DG2		62.3	HT Cooling Water Outlet Temperature	Health 62.3 (<80) and ETA unavailable; schedule inspection (htcw_engine_outlet_temp_c).	Sched next maint	N/A	MED
DG3		63.0	HT Cooling Water Outlet Temperature	Health 63.0 (<80) and ETA unavailable; schedule inspection (htcw_engine_outlet_temp_c).	Sched next maint	N/A	MED
DG4		65.1	Lube Oil Inlet Temperature	ETA 55.0d to limit (lo_inlet_temp_c).	Monitor (30d)	55.0d	LOW

Blackreef — AxiomIQ Analytics Report

Highest Priority Engine — Detailed Analysis (DG1) Executive Summary

Engine DG1 is currently operating within defined limits, with an overall health score of 62.3 out of 100. Analysis indicates developing drift patterns rather than immediate failure conditions.

Key Developing Risk Indicators

HT Cooling Water Outlet Temperature (High Temperature Cooling Water) Trend: →
HTCW Outlet Temp • htcw_engine_outlet_temp_c
Observed trend suggests: Increasing HT cooling water outlet temperature may indicate reduced heat transfer, cooler fouling, or elevated engine thermal load.
Risk classification: Thermal stress and reduced margin
Estimated time to limits: min=N/A | max=N/A



Lube Oil Inlet Temperature (Lubrication Oil) Trend: →
LO Inlet Temp • lo_inlet_temp_c
Observed trend suggests: Rising lube oil inlet temperature can indicate reduced cooling efficiency, oil cooler fouling, or increased engine friction.
Risk classification: Accelerated wear and oil breakdown
Estimated time to limits: min=N/A | max=N/A



Charge Air Pressure (Air Intake / Turbocharging) Trend: →
Charge Air Press • charge_air_pressure_bar
Observed trend suggests: A sustained decline in charge air pressure may indicate intake restriction, air filter fouling, or reduced turbocharger efficiency.
Risk classification: Performance degradation leading to thermal stress
Estimated time to limits: min=N/A | max=N/A



Main Lube Oil Inlet Pressure (Main Lubrication System) Trend: →
Main LO Inlet Press • engine_lo_inlet_pressure_bar
Observed trend suggests: A gradual drop in lube oil inlet pressure can indicate filter loading, pump wear, or internal leakage.
Risk classification: Loss of lubrication margin
Estimated time to limits: min=N/A | max=N/A



Turbocharger Lube Oil Inlet Pressure (Turbocharger Lubrication) Trend: →
TC LO Inlet Press • tc_lo_inlet_pressure_bar
Observed trend suggests: Declining turbocharger lube oil pressure may suggest filter restriction or pump performance issues.
Risk classification: Turbocharger bearing wear
Estimated time to limits: min=N/A | max=N/A



Operational Recommendations

- No immediate shutdown or load reduction is recommended at this time.
- Prioritize inspection of the highest-risk subsystem during the next planned maintenance opportunity.
- Monitor key lubrication and cooling parameters for continued drift over the next 72 hours.
- Re-run AxiomIQ analysis after additional data is collected (ideally 7–14 days).