

Existing TA6585; paired outputs 5+6 and 7+8. Carrier is not a complete power/protection circuit.

#1/#1 pull-downs are on the IC side of series resistors. Motor current never returns through MCU wiring.

VM/DRIVE_GND from a separately qualified supply path. No direct battery/charger ground equivalence is implied.

7 A is NOT a board rating. Copper, current, temperature, power sequencing and actual logic levels need bench checks.

COMBINED PROPOSAL: motor at left, logic at right. No physical power/thermal qualification or fabrication release

H8 = qualified Waveshare +5V, H9 = XIAO BATO positive, H3/H5 = DRIVE_GND, No native USB VBUS wire.

VM remains the separately qualified motor supply. Never bridge VM, WAVE_5V, XIAO_BAT or raw battery terminals

U2 TP573701 and U3 MAX40200 are on the underside. Package/paste/via manufacture and actual PCB fit remains open.