

DOS COMMAND TO ASSEMBLING AND DEBUGE THE ASM FILE






TASK: 01

Big DOSBox 0.74-3, Cpu sp	eed: 3000 cyc	les, Frameskip	0, Progra	– 🗆 X
	19F5 IP 010	C Stack	•	s 7200
	19F5		+2 20CD	. IE OE 775 AE DE CE
	19F5 HS 19F 19F5 FS 19F		+4 9FFF OF DI +6 EAOO O (FIFSFZFAFPFCF 0100000
5 BOO 31 111E 33	1313 13131	 -	*0 L100 0	
CMD >			1 0	1234567
			DS:0100 B8 3	4 12 BB FC AB B9 00
9109 BA00B8 MDI	J DX,B800		DS:0108 B1 B	A 00 B8 01 D8 B8 00
919C 91D8 ADI			DS:0110 4C C	01 01 02 02 00
910E B8004C MO			DS:0118 89 50	
9111 CD21 IN'			DS:0120 F6 0	
9113 0431 ADI			DS:0128 D1 E	
9115 D2 DB	DZ		DS:0130 07 8	0 0. 00 00 20 .0 01
9116 3100 X01		. I	DS:0138 85 C	0 11 10 01 10 10 00
9118 8956E4 MOV			DS:0140 00 8	
911B 8946E6 MO	J [BP-1A],A	X	DS:0148 74 0	9 8B 46 F2 48 3B 46
0 1 2 3	4 5 6 7	8 9 A B	CDEF	
DS:0000 CD 20 FF 9F (90 EA FO FE	AD DE 1B 05	C5 06 00 00	= f.Ω≡∎ i+
DS:0010 18 01 10 01 :	18 01 92 01	01 01 01 00	02 FF FF FF	f
DS:0020 FF FF FF FF I	FF FF FF FF	FF FF FF FF	EB 19 CO 11	δ. ^L .
DS:0030 AZ 01 14 00 :	l8 00 F5 19	FF FF FF FF	00 00 00 00	6J
DS:0040 05 00 00 00 0	90 00 00 00	00 00 00 00	00 00 00 00	
1 Step 2ProcStep 3Re	etrieve 4Help	ON 5 BRK Me	ոս 6 7 սր	8 dn 9 le 10 ri

Task: 02



Task:03

