

Pump P-17 Routine Visual Inspection

Record ID: WB-GOLDEN-INSPECTION-001

Location: Fictional Maintenance Bay

Equipment: Generic centrifugal pump P-17

Inspection type: Routine visual inspection

Status: Draft observations - engineering verification pending

This document is synthetic and contains no operational or organization data.

Detailed observations are recorded on page 2.

Observed Conditions

1. LOWER OUTLET FLANGE

Localized orange surface corrosion was observed around the lower outlet flange. Remaining wall thickness was not available from the visual inspection.

2. SHAFT SEAL

A small dark oil seepage stain was observed directly below the shaft seal. Leak rate was not measured during this inspection.

3. COUPLING SAFETY GUARD

One attachment bolt was missing from the yellow coupling safety guard. The remaining visible fasteners were installed.

Required follow-up: Apply the approved pump maintenance SOP. Do not infer operating safety, wall thickness, leak rate, or repair approval from this visual record alone.