




Home Getting Started

**DrDuino Pioneer Schematics** 

## Return To Main Lab Area

Assembly Instructions	
How To Solder in 5 Easy Steps	~
A Quick Note From Dr. Duino	~
Pioneer Parts List	~
Push Buttons	~
Current Limiting Resistors	~
Potentiometers	~
Light Dependent Resistor (LDR)	~
Piezzo Buzzer	~
Discrete LED's	~
Arduino Uno Headers	~
Addressable LED	~
Pioneer Shield Mounting	~
Using The Remaining Header	~





## **Using The Remaining Header**



## **Parts Used In This Step**

Quantity	Description
1	8 Pin Header




Take the remaining header which was left over from earlier, and break this into a few more pieces.

- 1. Using your pliers break off 2 more pins.
- 2. Do this twice.
- 3. You will be left with two, 2-pin headers and one 4-pin header.
- 4. Now populate JP3 (2 pin header) and JP1 (4 pin header). The remaining 2 pin header can be

discarded. (Short side goes into the TOP of the pioneer, see photos below).







Powered by **KARTRA**