





Table of Laplace Transforms


Number	$F(s)$	$f(t), t \geq 0$
1	1	$\delta(t)$
2	$\frac{1}{s}$	$1(t)$
3	$\frac{1}{s^2}$	t
4	$\frac{2!}{s^3}$	t^2
5	$\frac{3!}{s^4}$	t^3
6	$\frac{m!}{s^{m+1}}$	t^m
7	$\frac{1}{(s+a)}$	e^{-at}
8	$\frac{1}{(s+a)^2}$	te^{-at}
9	$\frac{1}{(s+a)^3}$	$\frac{1}{2!}t^2e^{-at}$
10	$\frac{1}{(s+a)^m}$	$\frac{1}{(m-1)!}t^{m-1}e^{-at}$
11	$\frac{a}{s(s+a)}$	$1 - e^{-at}$
12	$\frac{a}{s^2(s+a)}$	$\frac{1}{a}(at - 1 + e^{-at})$
13	$\frac{b-a}{(s+a)(s+b)}$	$e^{-at} - e^{-bt}$
14	$\frac{s}{(s+a)^2}$	$(1-at)e^{-at}$
15	$\frac{a^2}{s(s+a)^2}$	$1 - e^{-at}(1+at)$
16	$\frac{(b-a)s}{(s+a)(s+b)}$	$be^{-at} - ae^{-at}$
17	$\frac{a}{(s^2+a^2)}$	$\sin at$
18	$\frac{s}{(s^2+a^2)}$	$\cos at$
19	$\frac{s+a}{(s+a)^2+b^2}$	$e^{-at}\cos bt$
20	$\frac{b}{(s+a)^2+b^2}$	$e^{-at}\sin bt$
21	$\frac{a^2+b^2}{s[(s+a)^2+b^2]}$	$1 - e^{-at} \left(\cos bt + \frac{a}{b} \sin bt \right)$

Design Aids

Closed Loop



Open Loop



Design Relations

$$\begin{aligned}
 t_s &= \frac{4.6}{\sigma} & t_r &= \frac{1.8}{\omega_n} \\
 \sigma &= \zeta \omega_n & \omega_d &= \omega_n \sqrt{1 - \zeta^2} \\
 e_{ss} &= \frac{1}{1 + K_0}, \quad K_0 = |G(j\omega)|_{\omega=0} \\
 |E| &< \frac{1}{1 + W_1}, \quad \omega < \omega_1 & \\
 \omega_{BW} &= \omega_c & \text{for } PM = 90^\circ \\
 \omega_{BW} &= 2\omega_c & \text{for } PM = 45^\circ \\
 M_r &\cong \frac{1}{2 \sin(PM/2)} \\
 M_p &= 5\%, \quad \zeta = 0.7 \\
 M_p &= 15\%, \quad \zeta = 0.5 \\
 M_p &= 35\%, \quad \zeta = 0.3 \\
 \zeta &\cong \frac{PM}{100} \quad \text{for } PM < 70^\circ
 \end{aligned}$$