

Wire on AK Max	Notes	Counted from	To SKR3 EZ	Notes	Notes
Extruder	E	From above: start down right		LV->HV bidirect card for strain gauge	
5V			5V (probe)	5V straight, 3V3 f WIFI t LV & 5V t HV f 5V(probe)	Strain Gauge i2C
SCL			PB15 (WIFI)	PB15->LV, HV->SCL	Strain Gauge i2C
SDA			PB14 (WIFI)	PB14->LV, HV-SDA	Strain Gauge i2C
LEVE			PE5 (servo)	LED	
x					
FAN0			FAN0	Part cooling, signal	.+V from 24V
x					
FAN1			FAN1	Hotend fläkt, signal	.+V from 24V
HEAT			PB3 on HE0	Hotend heater, signal	HEAT to same
24V			VBB on HE0	V to head	24V to same
24V			VBB on HE0	V to head	24V to same

24V			VBB on HE0	V to head	24V to same
HEAT			PB3 on HE0	Hotend heater, signal	HEAT to same
HEAT			PB3 on HE0	Hotend heater, signal	HEAT to same
GND			GND	GND Servo, PE5	
T0			TH0	Hotend termistor	Joint GND
GND			GND	GND Probe, PC13	
x					
x					
x					
x					
x					
X-axis	X	From above: start down right	XM		
F_OUT			PC2	Filament runout, E0DET	xxDET are unused
GND			GND	GND filament runout, E0DET	
x					
OB2			2B	Motor wiring, E	Low resistance between B pairs
OB1			2A	--	Infinite resitance between A & B
OA1			1A	--	Low resistance between A pairs
OA2			1B	--	Infinite resitance between A & B

3V3					Unused
X_SQ			PC1	Signal endstop, X-STOP	
GND			GND	GND endstop, X-STOPP	
OA2			1B	Motor wiring, X	
OA1			1A	--	
OB1			2A	--	
OB2			2B	--	
Y-axis	Y	From above, start down	YM		
x					
Y_SQ			PC3	Signal endstop, Y-STOPP	
GND			GND	GND endstop, Y-stop	
OA2			1B	Motor wiring, Y	
OA1			1A	--	
OB1			2A	--	
OB2			2B	--	
Z-axis	ZR, ZL	From above, start down	ZA		
3V3			5V?	Z-endstop	Only ZR connector, Unused
ZR_SQ			PC0	Signal endstop	Only ZR connector, Unused
GND			GND	GND endstop	Only ZR connector, Unused
OA2			1B	Motor wiring, Z	On both ZR and ZL
OA1			1A	--	
OB1			2A	--	
OB2			2B	--	
Other wires					
Mosfet-card 24V +/-		Thick + & -	DCIN		
Bed control wires		Thin + & -	BED	Tiny current	
T1		Bed-thermistor	TB		
LCD			-	Doesn't work with SKR3	
	=	Not used			