


Which manufacturing errors matter, under the real factory tolerances



Share of each metric's variation explained by one parameter. Resistors and copper thickness show no measurable effect on reflection or coupling.