
+5V
1
2
Conn_01x02_Socket
J1
GND
Power input to board
As many switches in parallel as desired;
activating one will kill motors.
+5V
PWR_FLAG
SW2
SW_Reed
SW1
SW_Reed
R1
220
1
2
J2
Conn_01x02_Socket
load
R2
1k
Q1
Q_NPN
220
R3
PWR_FLAG
LED lit = motors killed
D2 LED
GND