DTC P2455:00 [SKYACTIV-D 1.5]

id019YA

DTC P2455:00	Exhaust gas pressure sensor No.2 circuit high input

more than V

- Exhaust gas pressure sensor No.2 connector or terminals malfunction
- PCM connector or terminals malfunction
- Short to power supply in wiring harness between exhaust gas pressure sensor No.2 terminal C and PCM

POSSIBLE CAUSE

DTC P2455:00

STEP