POSSIBLE CAUSE	• CAN bus communication line malfunction • PCM malfunction

DTC
U0121:00