WATER-COOLED CHARGE AIR COOLER INSPECTION [SKYACTIV-D 1.5]

id0113q2702600

1. Inspect the water-cooled charge air cooler for coolant leakage. (See WATER-COOLED CHARGE AIR COOLER COOLANT LEAKAGE INSPECTION [SKYACTIV-D 1.5].)
   - If there is a malfunction in the water-cooled charge air cooler, replace it. (See WATER-COOLED CHARGE AIR COOLER REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)