HEATED OXYGEN SENSOR (HO2S) REMOVAL/INSTALLATION [SKYACTIV-G 1.3, SKYACTIV-G 1.5]

id0140q1804000

Warning

- **A hot engine and exhaust system can cause severe burns. Turn off the engine and wait until they**