EXCESSIVE CREEP [EW6A-EL]

id050322100700

TROUBLESHOOTING ITEM	**Excessive creep**
DESCRIPTION	• Vehicle accelerates in D and R position when accelerator pedal is not depressed.
POSSIBLE CAUSE	1. Not within idle speed specification

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**INSPECT ENGINE CONTROL SYSTEM FOR MALFUNCTION** • Perform the symptom troubleshooting “NO.14 FAST IDLE/RUNS ON”. (See NO.14 FAST IDLE/RUNS ON [SKYACTIV-D 1.5].) • Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Symptom troubleshooting is completed.