DTC U0010:88, U0155:00 [FULL-AUTO AIR CONDITIONER]

id0702c1073700

System malfunction location	• U0010:88: Unit communication error (MS-CAN) • U0155:00: Communication error with instrument cluster
Detection condition	**U0010:88** • The climate control unit detects a CAN bus communication line (MS-CAN) malfunction. **U0155:00** • The climate control unit could not receive CAN signal from the instrument cluster for **5 s or more**.
Fail-safe function	Not applicable
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN line between the climate control unit and instrument cluster
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5].)(See FOREWORD [SKYACTIV-D 1.5].)