DTC U0100:00 [STANDARD DEPLOYMENT CONTROL SYSTEM]

id0802b1004900

System malfunction location	• PCM communication error
Detection condition	• The SAS control module does not receive CAN signal from PCM for **5 s or more**, or receives CAN signal error from PCM for **0.4 s**.
Fail-safe function	Not applicable
Possible cause	• Malfunction in CAN line between the SAS control module and PCM • PCM malfunction • SAS control module malfunction
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 1.5].)