DTC U0001:88/U0155:00 [STANDARD DEPLOYMENT CONTROL SYSTEM]

id0802b1824100

System malfunction location	• U0001:88: Module communication error (HS-CAN) • U0155:00: Communication error with instrument cluster
Detection condition	**U0001:88** • The SAS control module detects a CAN communication line (HS-CAN) error. **U0155:00** • The SAS control module could not receive CAN signal from the instrument cluster for **5 s or more**.
Fail-safe function	Not applicable
Possible cause	• Malfunction in CAN bus communication line • Malfunction in CAN line between the SAS control module and instrument cluster
System wiring diagram	Not applicable

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5].)(See FOREWORD [SKYACTIV-D 1.5].))