• Door locking operation inhibited while under i-stop control. (With i-stop system)

Possible cause

Diagnostic Procedure

Step