HIGH BEAM CONTROL (HBC) SYSTEM DOES NOT OPERATE [HIGH BEAM CONTROL (HBC) SYSTEM]

id0903p0021500

Description

- High beam control (HBC) system does not operate

Possible malfunction

Note

- Under the following conditions, the ability of the forward sensing camera (FSC) to detect light-emitting objects decreases, which could result in the system not operating normally and the inability to detect vehicles ahead.
  - Brightness of moonlight in surrounding area
  - Poor visibility due to rain and fog
  - Scratches or dirt on the camera lens or windshield glass