



PC PRO INSPECTIONS

6185994446

paul@pcproinspections.com



PC PRO RESIDENTIAL INSPECTION

1234 Main Street
Fairfield , IL 62837

Buyer Name

06/13/2026 9:00AM



Inspector

Paul Cantrell

Paul Cantrell

InterNACHI's certified home inspector

6185994446

paul@pcproinspections.com



Agent

Agent Name

555-555-5555

agent@spectora.com

TABLE OF CONTENTS

1: Inspection Detail	5
2: Roof	6
3: Exterior	10
4: Basement, Foundation, Crawlspace & Structure	15
5: Foundation Slab	18
6: Electrical	19
7: Cooling east	22
8: Cooling west	24
9: Attached Garage	25
10: Plumbing basement	28
11: Plumbing garage	30
12: Out Building	33
13: Heating basement	35
14: Heating	36
15: Living room	37
16: Kitchen	40
17: Kitchen Pantry	42
18: Dining Room	43
19: Hallway Main Floor	44
20: Master Bedroom downstairs	46
21: Master Bedroom Closet	48
22: Master Bathroom	49
23: Bedroom 2 west	50
24: Bathroom 2 off of laundry room	53
25: Bedroom 3 master upstairs	54
26: Bedroom 4 east	56
27: Bathroom 3	58
28: Bedroom 5	60

29: Laundry	62
30: Attic, Insulation & Ventilation	64
31: Hallway 2nd Floor	65
32: Interior Stairway	67
33: Maintenance Items	68
Standards of Practice	69

SUMMARY

- 🔧 2.1.1 Roof - Roof Covering: Cracked and Damaged Roof Covering
- 🔧 2.1.2 Roof - Roof Covering: Tree Too Close
- 🔧 3.3.1 Exterior - Wall-Covering, Flashing & Trim: Broken/cracked siding
- 🔧 3.6.1 Exterior - GFCIs & Electrical: Missing GFCI
- 🔧 3.6.2 Exterior - GFCIs & Electrical: Missing cover
- 🔧 3.11.1 Exterior - Windows: Damaged Window Screen
- 🔧 5.1.1 Foundation Slab - Foundation Slab: Minor crack
- 🔧 6.6.1 Electrical - Panelboards & Breakers: Panel needs cover put on
- 🔧 6.6.2 Electrical - Panelboards & Breakers: Switches and junction boxes need covers
- 🔧 9.1.1 Attached Garage - Garage Floor: Cracked Concrete at Garage Floor
- 🔧 16.1.1 Kitchen - Kitchen Sink: Defect at Sink Fixture
- 🔧 23.1.1 Bedroom 2 west - Doors: Door Doesn't Latch
- 🔧 23.3.1 Bedroom 2 west - Switches, Fixtures & Receptacles: Cover Not In Place
- 🔧 23.4.1 Bedroom 2 west - Floors, Walls, Ceilings: Minor Corner Cracks
- 🔧 26.1.1 Bedroom 4 east - Doors: Door Doesn't Latch
- 🔧 27.7.1 Bathroom 3 - Doors: Door Sticks
- 🔧 29.1.1 Laundry - Clothes Washer: Clean filter
- 🔧 31.3.1 Hallway 2nd Floor - Floors, Walls, Ceilings: Previous repair
- 🔧 32.1.1 Interior Stairway - Stairs, Steps, Stoops, Stairways & Ramps: Wall crack
- 🔧 33.2.1 Maintenance Items - Home Maintenance: HVAC Maintenance

1: INSPECTION DETAIL

Information

General Inspection Info: In Attendance

Home Owner
I prefer to have my client with me during my inspection so that we can discuss concerns, and I can answer all questions.

General Inspection Info: Occupancy
Occupied

General Inspection Info: Weather Conditions
Sunny, Dry, Hot

General Inspection Info: Type of Building
Single Family

2: ROOF

Information

Roof Covering: Type of Roof-Covering Described

Asphalt

I observed the roof-covering material and attempted to identify its type.

This inspection is not a guarantee that a roof leak in the future will not happen. Roofs leak. Even a roof that appears to be in good, functional condition will leak under certain circumstances. We will not take responsibility for a roof leak that happens in the future. This is not a warranty or guarantee of the roof system.



Roof Covering: Roof Was Inspected

Ground, Drone

We attempted to inspect the roof from various locations and methods, including from the ground and a ladder.

The inspection was not an exhaustive inspection of every installation detail of the roof system according to the manufacturer's specifications or construction codes. It is virtually impossible to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our inspection. We recommend that you ask the sellers to disclose information about the roof, and that you include comprehensive roof coverage in your home insurance policy.

Flashing: Eaves, Gables and Wall Intersections

I looked for flashing installed at the eaves (near the gutter edge) and at the gables (the diagonal edge of the roof). There should be metal drip flashing material installed in these locations. The flashing helps the surface water on the roof to discharge into the gutter. Flashing also helps to prevent water intrusion under the roof-covering.




Plumbing Vent Pipes: Plumbing Vent Pipes Inspected

I looked at DWV (drain, waste and vent) pipes that pass through the roof covering. There should be watertight flashing (often black rubber material) installed around the vent pipes. These plumbing vent pipes should extend far enough above the roof surface.



North



Flue Gas Vent Pipes: Flue Gas Vent Pipe Inspected

I looked at flue gas vent pipes that pass through the roof covering.

All gas-fired appliances must be connected to venting systems. There should be watertight metal flashing installed around the flue gas vent pipes. The vent pipes should extend far enough above the roof surface.



Roof Vents: Roof vents



Limitations

Roof Covering

UNABLE TO SEE EVERYTHING

This is a visual-only inspection of the roof-covering materials. It does not include an inspection of the entire system. There are components of the roof that are not visible or accessible at all, including the underlayment, decking, fastening, flashing, age, shingle quality, manufacturer installation recommendations, etc.

Roof Covering

UNABLE TO WALK UPON ROOF SURFACE

According to the Home Inspection Standards of Practice, a home inspector is not required to walk upon any roof surface. However, as courtesy only, I attempted to walk upon the roof surface, but was unable. It was not safe. It was not accessible. This was a restriction to my inspection of the roof system. You may want to consider hiring a professional roofer with a lift to check your roof system.

Flashing

DIFFICULT TO SEE EVERY FLASHING

I attempted to inspect the flashing related to the vent pipes, wall intersections, eaves and gables, and the roof-covering materials. In general, there should be flashing installed in certain areas where the roof covering meets something else, like a vent pipe or siding. Most flashing is not observable, because the flashing material itself is covered and hidden by the roof covering or other materials. So, it's impossible to see everything. A home inspection is a limited visual-only inspection.

Plumbing Vent Pipes

UNABLE TO REACH ALL THE PIPES

I was unable to closely reach and observe all of the vent pipes that pass through the roof-covering materials. This was an inspection restriction.

Flue Gas Vent Pipes

UNABLE TO REACH ALL THE FLUE GAS VENT PIPES

I was unable to closely reach and observe all of the flue gas vent vent pipes that pass through the roof-covering materials. This was an inspection restriction.

Recommendations

2.1.1 Roof Covering

CRACKED AND DAMAGED ROOF COVERING

I observed areas of cracked/splitting and damaged roof-covering materials. This is a major defect. Prone to water leaking into the house. I recommend that a qualified roofing contractor to further evaluate and make repairs to the roof system,.

Recommendation

Contact a qualified roofing professional.



Maintenance Item



South

2.1.2 Roof Covering

Maintenance Item

TREE TOO CLOSE

I observed indications that a tree and/ tree branch where overhanging the roof and maybe in contact with it. I recommend cutting back the branches to not come in contact with the home.

Recommendation

Contact a qualified tree service company.



West

3: EXTERIOR

Information

General: Exterior Was Inspected

I inspected the exterior of the house.

Eaves, Soffits & Fascia: Eaves, Soffits and Fascia Were Inspected

I inspected the eaves, soffits and fascia. I was not able to inspect every detail, since a home inspection is limited in its scope.



Wall-Covering, Flashing & Trim: Type of Wall-Covering Material Described

Vinyl

The exterior of your home is slowly deteriorating and aging. The sun, wind, rain and temperatures are constantly affecting it. Your job is to monitor the house's exterior for its condition and weathertightness.

Check the condition of all exterior wall-covering materials and look for developing patterns of damage or deterioration.

Vegetation, Surface Drainage, Retaining Walls & Grading: Vegetation, Drainage, Walls & Grading Were Inspected

I inspected the vegetation, surface drainage, retaining walls and grading of the property, where they may adversely affect the structure due to moisture intrusion.

GFCIs & Electrical: Ground Fault Circuit Interrupters

GFCIs & Electrical: Inspected GFCIs

I inspected ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible.



South

Walkways & Driveways: Walkways & Driveways Were Inspected

I inspected the walkways and driveways that were adjacent to the house. The walkways, driveways, and parking areas that were far away from the house foundation were not inspected.



Stairs, Steps, Stoops, Stairways & Ramps: Stairs, Steps, Stoops, Stairways & Ramps Were Inspected

I inspected the stairs, steps, stoops, stairways and ramps that were within the scope of my home inspection.

All treads should be level and secure. Riser heights and tread depths should be as uniform as possible. As a guide, stairs must have a maximum riser of 7-3/4 inches and a minimum tread of 10 inches.



Porches, Patios, Decks, Balconies & Carports: Porches, Patios, Decks, Balconies & Carports Were Inspected

I inspected the porches, patios, decks, balconies and carports at the house that were within the scope of the home inspection.



Railings, Guards & Handrails: Railings, Guards & Handrails Were Inspected

I inspected the railings, guards and handrails that were within the scope of the home inspection.



Windows: Windows Inspected

A representative number of windows from the ground surface was inspected.

Exterior Doors: Exterior Doors Inspected

I inspected the exterior doors.



South

Exhaust Hoods: Dryer Exhaust Vent

Inspected the Dryer Exhaust Vent



Northwest

Spigots: Spigots

I have inspected all of the accessible spigots.



Northeast

Limitations

Eaves, Soffits & Fascia

INSPECTION WAS RESTRICTED

I did not inspect all of the eaves, soffit, and fascia. It's impossible to inspect those areas closely during a home inspection. A home inspection is not an exhaustive evaluation. My inspection of the exterior was limited. I did not reach and access closely every part of the eaves, soffit, and fascia.

Wall-Covering, Flashing & Trim

INSPECTION WAS RESTRICTED

I did not inspect all of the exterior wall-covering material. A home inspection is not an exhaustive evaluation. My inspection of the exterior was limited. I did not reach and access closely every part of the exterior wall-covering.

GFCIs & Electrical

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the GFCI system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Windows

INSPECTION RESTRICTED

I did not inspect all windows. I did inspect a representative number of them. It's impossible to inspect every window component closely during a home inspection. A home inspection is not an exhaustive evaluation. I did not reach and access closely every window, particularly those above the first floor level.

Recommendations

3.3.1 Wall-Covering, Flashing & Trim

BROKEN/CRACKED SIDING

Maintenance Item

I observed broken/ cracked siding. I recommend sealing the gaps or replacing the siding.

Recommendation

Recommended DIY Project



Southwest



West

3.6.1 GFCIs & Electrical

MISSING GFCI

Maintenance Item

I observed indications that a GFCI is missing in an area that is required to keep people safe.

Recommendation

Contact a qualified electrical contractor.



North

3.6.2 GFCIs & Electrical

MISSING COVER

I observed a GFCI missing it's cover.

 Maintenance Item



North

3.11.1 Windows

DAMAGED WINDOW SCREEN

I observed a damaged window screen.

Correction and further evaluation is recommended.

Recommendation

Contact a qualified handyman.

 Maintenance Item



South

4: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

Information

Basement: Basement Perimeter Foundation Material

Concrete

Basement: Basement Was Inspected

The basement was inspected according to the [Home Inspection Standards of Practice](#).
The basement can be a revealing area in the house and often provides a general picture of how the entire structure works. In most basements, the structure is exposed overhead, as are the HVAC distribution system, plumbing supply and DWV lines, and the electrical branch-circuit wiring. I inspected those systems and components.

Basement: Foundation Was Inspected

The foundation was inspected according to the [Home Inspection Standards of Practice](#).

Basement: Structural Load-Bearing Components Were Inspected

Structural components were inspected according to the [Home Inspection Standards of Practice](#), including readily observed floor joists.

Basement: Overhead Floor Structure

Wood Truss Joists, Wood Beam

Basement: Inspected for Water Stains

Where surfaces are visible, the inspector looked for obvious visual water stains. However, the presence of insulation or finished surface materials could prevent visibility of stains. According to the InterNACHI Home Inspection Standards of Practice, the inspector is not expected or required to remove or create visibility, where restrictions are present.

Exterior View Foundation: Foundation Exterior Inspected

All readily available and easily accessible exterior foundation walls were inspected. Any defects would be noted..

Exterior View Foundation: Common Hairline Cracks

Monitor



Exterior View Foundation: Structural Support Posts Inspected
Not Applicable

Exterior View Foundation: Waterproofing Visible?
Not Applicable

Slab on Grade Foundation: Slab Inspected

The visible portions of the concrete slab-on-grade foundation were inspected.



Insulation in Foundation/Basement Area: Insulation Was Inspected

During the home inspection, I inspected for insulation in unfinished spaces, including attics, crawlspaces and foundation areas. I inspected for ventilation of unfinished spaces, including attics, crawlspaces and foundation areas. And I inspected mechanical exhaust systems in the kitchen, bathrooms and laundry area.

I attempted to describe the type of insulation observed and the approximate average depth of insulation observed at the unfinished attic floor area or roof structure.

I reported as in need of correction the general absence of insulation or ventilation in unfinished spaces.

Insulation in
Foundation/Basement Area: Type
of Insulation Observed

None

Insulation in Foundation/Basement Area: Walls Approximate Insulation

Not Required

Determining how much insulation should be installed in a house depends upon where a home is located. proper amount of insulation should be installed at a particular area of a house is dependent upon which climate zone the house is located.

This house is located in a climate zone that requires an R-value of


Insulation in Foundation/Basement Area: Insulation Location	Insulation in Foundation/Basement Area: Floor Approximate Insulation
Absent	Absent

Ventilation in Foundation/Basement Area: Ventilation Inspected

During the home inspection, I inspected for ventilation in unfinished spaces, including attics, crawlspaces and foundation areas. And I inspected mechanical exhaust systems in the kitchen, bathrooms and laundry area.

I report as in need of correction the general absence of ventilation in unfinished spaces.

Basement Electrical: Basement
Electrical Inspected



Basement Electrical: Inspected
Lights

Basement Electrical: Receptacles
& GFCI Protection
None

Basement Electrical: Wiring

Limitations

Slab on Grade Foundation

VISUAL LIMITATIONS

Concrete slab visibility is limited to areas above ground and not covered with exterior finishing materials.

5: FOUNDATION SLAB

Information

Foundation Slab: Foundation Slab

The foundation slab was in satisfactory condition at the time of inspection.

Limitations

Foundation Slab

I WAS UNABLE TO SEE EVERYTHING

I was unable to see everything at the time of inspection

Recommendations

5.1.1 Foundation Slab

MINOR CRACK

Recommendation

Contact a qualified professional.

 Maintenance Item



Northwest

6: ELECTRICAL

Information

Service Mast, Service Conduit & Raceway: Inspected the Service Mast, Service Conduit & Raceway

I inspected the electrical service mast, service conduit and raceway.



Electric Meter & Base: Inspected the Electric Meter & Base

I inspected the electrical electric meter and base.



Service-Entrance Conductors: Inspected Service-Entrance Conductors

I inspected the electrical service-entrance conductors.

Main Service Disconnect: Homeowner's Responsibility

It's your job to know where the main electrical panel is located, including the main service disconnect that turns everything off.

Be sure to test your GFCIs, AFCIs, and smoke detectors regularly. You can replace light bulbs, but more than that, you ought to hire an electrician. Electrical work is hazardous and mistakes can be fatal. Hire a professional whenever there's an electrical problem in your house.

Main Service Disconnect: Inspected Main Service Disconnect

I inspected the electrical main service disconnect.



Main Service Disconnect: Main Disconnect Rating, If Labeled

200

I observed indications of the main service disconnect's amperage rating. It was labeled.

Electrical Wiring: Type of Wiring, If Visible

NM-B (Romex)

Panelboards & Breakers: Inspected Main Panelboard & Breakers

I inspected the electrical panelboards and over-current protection devices (circuit breakers and fuses).


Panelboards & Breakers: Inspected Subpanel & Breakers

I inspected the electrical subpanel and over-current protection devices (circuit breakers and fuses).



Service Grounding & Bonding: Inspected the Service Grounding & Bonding

I inspected the electrical service grounding and bonding.



Limitations

Electrical Wiring

UNABLE TO INSPECT ALL OF THE WIRING

I was unable to inspect all of the electrical wiring. Obviously, most of the wiring is hidden from view within walls. Beyond the scope of a visual home inspection.

Service Grounding & Bonding

UNABLE TO CONFIRM PROPER GROUNDING AND BONDING

I was unable to confirm proper installation of the system grounding and bonding according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the grounding and bonding as much as I could according to the Home Inspection Standards of Practice.

Recommendations


6.6.1 Panelboards & Breakers

PANEL NEEDS COVER PUT ON

Recommendation

Contact a qualified professional.

 Recommendation



Basement

6.6.2 Panelboards & Breakers

SWITCHES AND JUNCTION BOXES NEED COVERS


Recommendation

Contact a qualified professional.

 Maintenance Item



Basement



Basement



Basement



Basement

7: COOLING EAST

Information

Cooling System Information: Service Disconnect Inspected

I observed a service disconnect within sight of the cooling system.



Cooling System Information: Info tag



Thermostat and Normal Operating Controls: Thermostat Location

Living room



Ductwork: Ductwork Installed

Non-insulated

I observed ductwork in the house. Air conditioning (cooling) systems, including heat pump systems, use ductwork to distribute the cooled, conditioned air throughout the house. I will attempt to determine if the each room has a cooling source or conditioned-air supply, but I may not be able to find every duct register.

8: COOLING WEST

Information

Cooling System Information: Service Disconnect Inspected

I observed a service disconnect within sight of the cooling system.



Cooling System Information: Info tag



Thermostat and Normal Operating Controls: Thermostat Location

Laundry room



Ductwork: Ductwork Installed

Non-insulated

I observed ductwork in the house. Air conditioning (cooling) systems, including heat pump systems, use ductwork to distribute the cooled, conditioned air throughout the house. I will attempt to determine if the each room has a cooling source or conditioned-air supply, but I may not be able to find every duct register.

9: ATTACHED GARAGE

Information

Garage Floor: Garage Floor Inspected I inspected the floor of the attached garage.	Garage Vehicle Door: Type of Door Operation Opener
Garage Vehicle Door Opener: Manual Release I checked for a manual release handle--a means of manually detaching the door from the door opener. The handle should be colored red so that it can be seen easily. The handle should be easily accessible and no more than 6 feet above the garage floor. The handle should not be in contact with the top of a vehicles.	
Garage Vehicle Door Opener: Garage Door Panels Were Inspected I inspected the garage door panels.	
Garage Vehicle Door Opener: Spring Warning Label Was Inspected I observed no spring warning label attached to the spring assembly or the back of the door panel.	
Garage Vehicle Door Opener: General Warning Label Was Inspected I observed a general warning label attached to the back of the door panel. Good.	
Garage Vehicle Door Opener: Bottom Bracket Label Was Inspected I observed two warning labels attached to the door in the vicinity of the bottom corner brackets. Some newer doors have tamper-resistant bottom corner brackets that do not require these warning labels.	
Garage Vehicle Door Opener: Wall Control Button Label Was Inspected I observed no warning label near the wall control button.	
Garage Vehicle Door Opener: Springs, Bracket & Hardware Were Inspected I closed the door and checked the springs for damage. If a spring was broken, operating the door can cause serious injury or death. I would not operate the door if there was damage. I visually checked the doors hinges, brackets and fasteners. If the door had an opener, the door must have an opener-reinforcement bracket that is securely attached to the doors top section. The header bracket of the opener rail must be securely attached to the wall or header using lag bolts or concrete anchors.	

Garage Vehicle Door Opener: Door Was Manually Opened and Closed

I closed the door. If the door had an opener, I pulled the manual release to disconnect the door from the opener. I lifted and operated the door. If the door was hard to lift, then it is out of balance. This is an unsafe condition.

I raised the door to the fully-open position, then closed the door. The door should move freely, and it should open and close without difficulty. As the door operates, I make sure that the rollers stay in the track. The door should stay in the fully open position. The door should also stay in a partially opened position about three to four above the garage floor level.

I reconnected the door to the opener, if present.

I checked the door handles or gripping points.

Garage Vehicle Door Opener: Spring Containment Was Inspected

If the door has extension springs, I inspect for spring containment. Extension springs should be contained by a cable that runs through the center of the springs. If a spring breaks, containment helps to prevent broken parts from flying around dangerously in the garage.

Garage Vehicle Door Opener: Wall Push Button Was Inspected

I inspected the wall button. The wall button should be at least 5 feet above the standing surface, and high enough to be out of reach of small children. I pressed the push button to see if it successfully operated the door.

Ceiling, Walls & Firewalls in Garage: Garage Ceiling & Walls Were Inspected


I inspected the ceiling and walls of the garage according to the Home Inspection Standards of Practice.

Ceiling, Walls & Firewalls in Garage: Door Between Garage and House Was Inspected

I inspected the door between the attached garage and the house.

The door should be a solid wood door at least 1-3/8 inches thick, a solid or honeycomb-core steel door at least 1-3/8 inches thick, or a 20-minute fire-rated door.

The door should be equipped with a self-closing or an automatic-closing device.



Ceiling, Walls & Firewalls in Garage: Floors, Walls, and Ceiling

Limitations

Garage Floor

CAN'T SEE EVERYTHING

I can not observe everything. Inspection restrictions. My inspection was limited.



Garage Vehicle Door Opener

UNABLE TO INSPECT GARAGE DOOR OPENER

I was unable to inspect the garage door opener. Inspection restriction.

Recommendations

9.1.1 Garage Floor

CRACKED CONCRETE AT GARAGE FLOOR

 Maintenance Item

I observed indications of cracks in the garage concrete floor. Monitor these cracks, if they become larger or heave/ settle, contact a concrete professional.

Recommendation
Recommend monitoring.



10: PLUMBING BASEMENT

Information

Main Water Shut-Off Valve:
Location of Main Shut-Off Valve
Basement



Basement


Water Supply : Water Supply Is Public

The water supply to the house appeared to be from the public water supply source based upon the observed indications at the time of the inspection. To confirm and be certain, I recommend asking the homeowner for details.

Main Fuel Supply Shut-Off Valve:
Location of Main Shut-Off Valve
Side of House

Hot Water Source: Type of Hot Water Source
Gas-Fired Hot Water Tank, Propane

I inspected for the main source of the distributed hot water to the plumbing fixtures (sinks, tubs, showers). I recommend asking the homeowner for details about the hot water equipment and past performance.



Water Supply & Distribution Systems: Inspected Water Supply & Distribution Pipes

I attempted to inspect the water supply and distribution pipes (plumbing pipes). Not all of the pipes and components were accessible and observed. Inspection restriction. Ask the homeowner about water supply, problems with water supply, and water leaks in the past.



Drain, Waste, & Vent Systems: Inspected Drain, Waste, Vent Pipes

I attempted to inspect the drain, waste, and vent pipes. Not all of the pipes and components were accessible and observed. Inspection restriction. Ask the homeowner about water and sewer leaks or blockages in the past.

Limitations

Water Supply & Distribution Systems

NOT ALL PIPES WERE INSPECTED

The inspection was restricted because not all of the water supply pipes were exposed, readily accessible, and observed. For example, most of the water distribution pipes, valves and connections were hidden within the walls.

Drain, Waste, & Vent Systems

NOT ALL PIPES WERE INSPECTED

The inspection was restricted because not all of the pipes were exposed, readily accessible, and observed. For example, most of the drainage pipes were hidden within the walls.

11: PLUMBING GARAGE

Information

Main Water Shut-Off Valve:
Location of Main Shut-Off Valve
Garage



Water Supply : Water Supply Is Public
The water supply to the house appeared to be from the public water supply source based upon the observed indications at the time of the inspection. To confirm and be certain, I recommend asking the homeowner for details.

Main Fuel Supply Shut-Off Valve:
Location of Main Shut-Off Valve
Side of House



West

Hot Water Source: Type of Hot Water Source

Thankless Hot Water, Propane

I inspected for the main source of the distributed hot water to the plumbing fixtures (sinks, tubs, showers). I recommend asking the homeowner for details about the hot water equipment and past performance.



Hot Water Source: Inspected Hot Water Source

I inspected the hot water source and equipment according to the [Home Inspection Standards of Practice](#).

Hot Water Source: Inspected TPR Valve

I inspected the temperature and pressure relief valve.



Water Supply & Distribution Systems: Inspected Water Supply & Distribution Pipes

I attempted to inspect the water supply and distribution pipes (plumbing pipes). Not all of the pipes and components were accessible and observed. Inspection restriction. Ask the homeowner about water supply, problems with water supply, and water leaks in the past.



Drain, Waste, & Vent Systems: Inspected Drain, Waste, Vent Pipes

I attempted to inspect the drain, waste, and vent pipes. Not all of the pipes and components were accessible and observed. Inspection restriction. Ask the homeowner about water and sewer leaks or blockages in the past.

Limitations

Water Supply & Distribution Systems

NOT ALL PIPES WERE INSPECTED

The inspection was restricted because not all of the water supply pipes were exposed, readily accessible, and observed. For example, most of the water distribution pipes, valves and connections were hidden within the walls.

Drain, Waste, & Vent Systems

NOT ALL PIPES WERE INSPECTED

The inspection was restricted because not all of the pipes were exposed, readily accessible, and observed. For example, most of the drainage pipes were hidden within the walls.

12: OUT BUILDING

Information

General: Garage Type

Detached, Pole Barn

Roof Information: Inspection Method

Ground, Drone

It is not required for a home inspector to climb a roof if the task is deemed unsafe by the inspector. Conditions at the time of the inspection may prevent inspection from the roof surface. If the conditions prevent an inspection from the roof surface a drone may be used. The use of a drone is not always an option due to FAA regulations. The inspector will attempt all available options to provide as much detail as possible given the conditions.

Roof Information: Roof Pitch

Medium Slope

**Roof Information: Roof
Type/Style**

Gable

Outbuilding Roof: Material Approximate Age

Unknown

The age of roof material is an approximation based on the opinion of the inspector. The roofing materials age may not be exact based on the visual appearance of the material and not the actual date of installation. The approximate is used to help the reader understand how much remaining life is to be expected given the average life span of the identified materials.

Outbuilding Roof: Material Type

Metal

Roofing materials have varying lifespans. Materials listed have the following average life expectancy based on manufacturer data.

3-Tab Asphalt 20-25 years

Architectural asphalt 25-30 years

Slate 125 years

Wood 20-60 years

EPDM 22-35 years

Modified BITUMEN 20 years

Cement/Clay tile 50-100 years

Metal 40-70 years

Outbuilding Roof: Layers of Material

1

The number of layers may not be exact. Layers of the material may be concealed by outer layers. Most manufacturers recommend 1 layer of material. When it comes time to replace the roofing, consult with the local building inspector as to local codes governing layers of roofing allowed at that time.

Outbuilding Roof: Valley Type

None

**Roof Drainage Systems: Gutter
Material**

Aluminum

Floor: Floor Material
Concrete



Walls: Wall Material
Wood Framed

Electrical: Electrical components present
Yes, Functional



Electrical: GFCI Protection
No

GFCI protection has evolved over the years as electrical codes change. GFCI protection may not have been required at the time of original construction. Updating to current codes may not be required, but is recommended to prevent injuries.

Electrical: Receptacles Open Ground/Reverse Polarity
Proper Polarity

Garage Door(s): Material
Insulated

Garage Door(s): Type
Up-and-Over

Overhead Door Opener:
Overhead door opener
Present, Operable

13: HEATING BASEMENT

Information

Heating System Information:
Energy Source
Gas

Heating System Information:
Heating Method
Heat Pump System

Heating System Information: Info
tag



Thermostat and Normal
Operating Controls: Thermostat
Location
Living room



Ductwork: Ductwork Installed
Non-insulated

I observed ductwork in the house. Warm-air heating systems, including heat pump systems, use ductwork to distribute the warm air throughout the house. I will attempt to determine if the each room has a heat source, but I may not be able to find every duct register.

Limitations

Heating System Information

HOT TEMPERATURE RESTRICTION

Because the outside temperature was too hot to operate the heating system without the possibility of damaging the system, I did not operate the heating system. Inspection restriction. Ask the homeowner about the system, including past performance.

14: HEATING

Information

Heating System Information: Energy Source Propane	Heating System Information: Heating Method Heat Pump System	Heating System Information: Info tag
---	---	---



**Thermostat and Normal
Operating Controls: Thermostat
Location**
Laundry room



Ductwork: Ductwork Installed
Insulated, Non-insulated

I observed ductwork in the house. Warm-air heating systems, including heat pump systems, use ductwork to distribute the warm air throughout the house. I will attempt to determine if the each room has a heat source, but I may not be able to find every duct register.

Limitations

Heating System Information

HOT TEMPERATURE RESTRICTION

Because the outside temperature was too hot to operate the heating system without the possibility of damaging the system, I did not operate the heating system. Inspection restriction. Ask the homeowner about the system, including past performance.

15: LIVING ROOM

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.

Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.


There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

General Requirements for Locations of Smoke Alarms and Carbon Monoxide Alarms

- Install smoke alarms inside each bedroom.
- For the best protection, interconnect all smoke alarms. When one smoke alarm sounds, they all sound.
- Smoke alarms should be installed at least 10 feet (3 meters) from a cooking appliance to minimize false alarms when cooking.
- Carbon monoxide alarms are required where dwelling units contain a fuel-fired appliance or have an attached garage with a door at the common wall between the dwelling unit and the garage.
- Carbon monoxide alarms are required to be located outside each separate sleeping area in the immediate vicinity of the bedrooms.
- Combination smoke-fire/carbon monoxide detectors are available.

There are two types of smoke alarms: ionization and photoelectric.

An ionization smoke alarm is generally more responsive to flaming fires, and a photoelectric smoke alarm is generally more responsive to smoldering fires. For the best protection, both types of alarms or combination ionization-photoelectric alarms, also known as dual-sensor smoke alarms, are recommended.



Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

16: KITCHEN

Information

Kitchen Sink: Ran Water at Kitchen Sink

I ran water at the kitchen sink.



Garbage Disposal: Turned On Garbage Disposal

I turned on the garbage disposal.

GFCI: GFCI Tested

I observed ground fault circuit interrupter (GFCI) protection in the kitchen.

Range/Oven/Cooktop: Turned On Stove & Oven

I turned on the kitchen's stove and oven.



Built-in Microwave: Microwave Turned On

I observed that the microwave turned on. I do nothing more than that. Microwaves are beyond the scope of a home inspection.

Refrigerator: Refrigerator Was On

I checked to see if the refrigerator was on. It was. That's all I inspected in relation to a refrigerator. Refrigerators are beyond the scope of a home inspection.

Exhaust Fan: Inspected Exhaust Fan

I inspected the exhaust fan in the kitchen. All mechanical exhaust fans should terminate outside. Confirming that the fan exhausts outside is beyond the scope of a home inspection.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Door: Exterior Door



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.



Recommendations

16.1.1 Kitchen Sink

DEFECT AT SINK FIXTURE

I observed a defect at the kitchen sink fixture.

Recommendation

Recommended DIY Project

 Maintenance Item




Kitchen

17: KITCHEN PANTRY

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

18: DINING ROOM


Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING


I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

19: HALLWAY MAIN FLOOR

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

20: MASTER BEDROOM DOWNSTAIRS

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.

Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

21: MASTER BEDROOM CLOSET

Information

Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

22: MASTER BATHROOM

Information

Bathroom Toilets: Toilets Inspected

I flushed all of the toilets.

Sinks, Tubs & Showers: Ran Water at Sinks, Tubs & Showers

I ran water at all bathroom sinks, bathtubs, and showers. I inspected for deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously.



GFCI & Electric in Bathroom: GFCI-Protection Tested

I inspected the GFCI-protection at the receptacle near the bathroom sink by pushing the test button at the GFCI device or using a GFCI testing instrument.

All receptacles in the bathroom must be GFCI protected.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

23: BEDROOM 2 WEST

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Closet: Closet

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.
There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

Recommendations

23.1.1 Doors

DOOR DOESN'T LATCH

 Maintenance Item

I observed that a door does not latch and close properly.
Recommendation
Contact a qualified handyman.




Closet door

23.3.1 Switches, Fixtures & Receptacles

COVER NOT IN PLACE

 Maintenance Item

I observed a receptacle with a cover (plate) that was not in place.
Recommendation
Contact a qualified professional.




23.4.1 Floors, Walls, Ceilings

 Maintenance Item

MINOR CORNER CRACKS

Minor cracks at the corners of doors and windows in walls. Appeared to be the result of long-term settling. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Recommendation
Contact a qualified professional.



24: BATHROOM 2 OFF OF LAUNDRY ROOM


Information

Bathroom Toilets: Toilets Inspected

I flushed all of the toilets.

Sinks, Tubs & Showers: Ran Water at Sinks, Tubs & Showers

I ran water at all bathroom sinks, bathtubs, and showers. I inspected for deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously.



Bathroom Exhaust Fan / Window: Inspected Bath Exhaust Fans

I inspected the exhaust fans of the bathroom(s). All mechanical exhaust fans should terminate outside. Confirming that the fan exhausts outside is beyond the scope of a home inspection.

GFCI & Electric in Bathroom: GFCI-Protection Tested


I inspected the GFCI-protection at the receptacle near the bathroom sink by pushing the test button at the GFCI device or using a GFCI testing instrument.

All receptacles in the bathroom must be GFCI protected.

Cabinetry, Ceiling, Walls & Floor: Floors, walls, and ceiling

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.




25: BEDROOM 3 MASTER UPSTAIRS

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house. You may purchase some here [HIS Home and Auto](#)

Closet: Closet

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

26: BEDROOM 4 EAST

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.



Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

Recommendations

26.1.1 Doors

DOOR DOESN'T LATCH

I observed that a door does not latch and close properly.

Recommendation

Contact a qualified handyman.

Maintenance Item



27: BATHROOM 3

Information

Bathroom Toilets: Toilets Inspected

I flushed all of the toilets.

Sinks, Tubs & Showers: Ran Water at Sinks, Tubs & Showers

I ran water at all bathroom sinks, bathtubs, and showers. I inspected for deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously.



Bathroom Exhaust Fan / Window: Inspected Bath Exhaust Fans

I inspected the exhaust fans of the bathroom(s). All mechanical exhaust fans should terminate outside. Confirming that the fan exhausts outside is beyond the scope of a home inspection.

GFCI & Electric in Bathroom: GFCI-Protection Tested

I inspected the GFCI-protection at the receptacle near the bathroom sink by pushing the test button at the GFCI device or using a GFCI testing instrument.

All receptacles in the bathroom must be GFCI protected.

Cabinetry, Ceiling, Walls & Floor: Floors, walls, and ceiling

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

Recommendations

27.7.1 Doors

DOOR STICKS

I observed that the door sticks.

Recommendation

Contact a qualified handyman.



Maintenance Item



28: BEDROOM 5

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.

Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).

Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Closet: Closet

Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.

There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

29: LAUNDRY

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.



Windows: Windows Inspected

I inspected a representative number of windows according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate window locks and operation features, which is beyond the scope of a home inspection.




Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Washer Stand Pipe: Standpipe

The standpipe for a clothes washer should be between 18 and 42 inches above the trap weir. The standpipe must also be trapped to prevent sewer gases from entering the home.



Limitations

Clothes Washer

DID NOT INSPECT

I did not inspect the clothes washer and dryer fully. These appliances are beyond the scope of a home inspection. I did not operate the appliances. The clothes dryer exhaust pipe must be inspected and cleaned every year to help prevent house fires.

Clothes Dryer

DID NOT INSPECT

I did not inspect the clothes washer and dryer fully. These appliances are beyond the scope of a home inspection. I did not operate the appliances. The clothes dryer exhaust pipe must be inspected and cleaned every year to help prevent house fires.

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Recommendations

29.1.1 Clothes Washer

CLEAN FILTER

Maintenance Item

Keeping your washer filter clean can remove odors and help your appliance run more efficiently.

30: ATTIC, INSULATION & VENTILATION

Information

Structural Components & Observations in Attic: Structural Components Were Inspected

Structural components were inspected from the attic space according to the [Home Inspection Standards of Practice](#).

Insulation in Attic: Type of Insulation Observed

Cellulose

Insulation in Attic: Approximate Average Depth of Insulation

6-9 inches, Unknown throughout the home

Determining how much insulation should be installed in a house depends upon where a home is located. The amount of insulation that should be installed at a particular area of a house is dependent upon which climate zone the house is located and the local building codes.

Ventilation in Attic: Ventilation Inspected

During the home inspection, I inspected for ventilation in unfinished spaces, including attics, crawlspaces and foundation areas. And I inspected for mechanical exhaust systems.

I report as in need of correction the general absence of ventilation in unfinished spaces.

Limitations

Structural Components & Observations in Attic

COULD NOT SEE EVERYTHING IN ATTIC

I could not see and inspect everything in the attic space. The access is restricted and my inspection is limited.

Ventilation in Attic

ROOF VENTS

Roof vents are installed but was unable to confirm they had holes cut in the attic.

31: HALLWAY 2ND FLOOR

Information

Doors: Doors Inspected

I inspected a representative number of doors according to the [Home Inspection Standards of Practice](#) by opening and closing them. I did not operate door locks and door stops, which is beyond the scope of a home inspection.

Switches, Fixtures & Receptacles: Inspected a Switches, Fixtures & Receptacles

I inspected a representative number of switches, lighting fixtures and receptacles.

Floors, Walls, Ceilings: Floors, Walls, Ceilings Inspected

I inspected the readily visible surfaces of floors, walls and ceilings. I looked for material defects according to the [Home Inspection Standards of Practice](#).


Presence of Smoke and CO Detectors: Inspected for Presence of Smoke and CO Detectors

I inspected for the presence of smoke and carbon-monoxide detectors.
There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

General Requirements for Locations of Smoke Alarms and Carbon Monoxide Alarms

- Install smoke alarms inside each bedroom.
- For the best protection, interconnect all smoke alarms. When one smoke alarm sounds, they all sound.
- Smoke alarms should be installed at least 10 feet (3 meters) from a cooking appliance to minimize false alarms when cooking.
- Carbon monoxide alarms are required where dwelling units contain a fuel-fired appliance or have an attached garage with a door at the common wall between the dwelling unit and the garage.
- Carbon monoxide alarms are required to be located outside each separate sleeping area in the immediate vicinity of the bedrooms.
- Combination smoke-fire/carbon monoxide detectors are available.

There are two types of smoke alarms: ionization and photoelectric.
An ionization smoke alarm is generally more responsive to flaming fires, and a photoelectric smoke alarm is generally more responsive to smoldering fires. For the best protection, both types of alarms or combination ionization-photoelectric alarms, also known as dual-sensor smoke alarms, are recommended.



Limitations

Switches, Fixtures & Receptacles

UNABLE TO INSPECT EVERYTHING

I was unable to inspect every electrical component or proper installation of the system according to modern code. A licensed electrician or township building code inspector could perform that type of test, which is beyond the scope of my visual-only home inspection. I inspected the electrical system as much as I could according to the Home Inspection Standards of Practice.

Presence of Smoke and CO Detectors

INSPECTED FOR PRESENCE OF SMOKE AND CO DETECTORS

I inspected for the presence of smoke and carbon-monoxide detectors.
There should be a smoke detector in every sleeping room, outside of every sleeping room, and one every level of a house.

Presence of Smoke and CO Detectors

UNABLE TO TEST EVERY DETECTOR

I was unable to test every detector. We recommend testing all of the detectors. Ask the seller about the performance of the detectors and of any issues regarding them. We recommend replacing all of the detectors (smoke and carbon monoxide) with new ones just for peace of mind and for safety concerns.

Recommendations

31.3.1 Floors, Walls, Ceilings

PREVIOUS REPAIR

Recommendation

Contact a qualified professional.

 Maintenance Item




32: INTERIOR STAIRWAY

Information

Stairs, Steps, Stoops, Stairways & Ramps: Stairs, Steps, Stoops, Stairways & Ramps Were Inspected

I inspected the stairs, steps, stoops, stairways and ramps that were within the scope of my home inspection.

All treads should be level and secure. Riser heights and tread depths should be as uniform as possible. As a guide, stairs must have a maximum riser of 7-3/4 inches and a minimum tread of 10 inches.



Recommendations

32.1.1 Stairs, Steps, Stoops, Stairways & Ramps

WALL CRACK

Recommendation

Contact a qualified professional.

Maintenance Item



Stairs

33: MAINTENANCE ITEMS

Recommendations

33.2.1 Home Maintenance

HVAC MAINTENANCE

 Maintenance Item

Regular HVAC maintenance is essential for ensuring your heating, ventilation, and air conditioning systems operate efficiently and effectively. By scheduling routine inspections and cleanings, you can prevent potential issues, extend the lifespan of your equipment, and improve indoor air quality. Simple tasks like changing air filters, checking for leaks, and verifying thermostat settings can make a significant difference in performance and energy consumption. Ultimately, investing time in HVAC maintenance can save you money on repairs and energy bills while keeping your home comfortable year-round. Our list of preferred contractors are listed at the bottom of this page.



Recommendation
Contact a qualified professional.

STANDARDS OF PRACTICE

Inspection Detail

Please refer to the [Home Inspection Standards of Practice](#) while reading this inspection report. I performed the home inspection according to the standards and my clients wishes and expectations. Please refer to the inspection contract or agreement between the inspector and the inspector's client.

Roof

Please refer to the [Home Inspection Standards of Practice](#) related to inspecting the roof of the house.

Monitor the roof covering because any roof can leak. To monitor a roof that is inaccessible or that cannot be walked on safely, use binoculars. Look for deteriorating or loosening of flashing, signs of damage to the roof covering and debris that can clog valleys and gutters.

Roofs are designed to be water-resistant. Roofs are not designed to be waterproof. Eventually, the roof system will leak. No one can predict when, where or how a roof will leak.

I. The inspector shall inspect from ground level or the eaves:

1. the roof-covering materials;
2. the gutters;
3. the downspouts;
4. the vents, flashing, skylights, chimney, and other roof penetrations; and
5. the general structure of the roof from the readily accessible panels, doors or stairs.

II. The inspector shall describe:

1. the type of roof-covering materials.

III. The inspector shall report as in need of correction:

1. observed indications of active roof leaks.

Exterior

Please refer to the [Home Inspection Standards of Practice](#) related to inspecting the exterior of the house.

I. The inspector shall inspect:

1. the exterior wall-covering materials;
2. the eaves, soffits and fascia;
3. a representative number of windows;
4. all exterior doors;
5. flashing and trim;
6. adjacent walkways and driveways;
7. stairs, steps, stoops, stairways and ramps;
8. porches, patios, decks, balconies and carports;
9. railings, guards and handrails; and
10. vegetation, surface drainage, retaining walls and grading of the property, where they may adversely affect the structure due to moisture intrusion.

II. The inspector shall describe:

1. the type of exterior wall-covering materials.

III. The inspector shall report as in need of correction:

1. any improper spacing between intermediate balusters, spindles and rails.

Basement, Foundation, Crawlspce & Structure**I. The inspector shall inspect:**

the foundation;
the basement;
the crawlspace; and
structural components.

II. The inspector shall describe:

the type of foundation; and
the location of the access to the under-floor space.

III. The inspector shall report as in need of correction:

observed indications of wood in contact with or near soil;
observed indications of active water penetration;
observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and
any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern.

Foundation Slab**I. The inspector shall inspect:**

the foundation;
the basement;
the crawlspace; and
structural components.

II. The inspector shall describe:

the type of foundation; and
the location of the access to the under-floor space.

III. The inspector shall report as in need of correction:

observed indications of wood in contact with or near soil;
observed indications of active water penetration;
observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and
any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern.

Electrical**I. The inspector shall inspect:**

1. the service drop;
2. the overhead service conductors and attachment point;
3. the service head, gooseneck and drip loops;
4. the service mast, service conduit and raceway;
5. the electric meter and base;
6. service-entrance conductors;
7. the main service disconnect;
8. panelboards and over-current protection devices (circuit breakers and fuses);
9. service grounding and bonding;
10. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible;
11. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible; and
12. for the presence of smoke and carbon-monoxide detectors.

II. The inspector shall describe:

1. the main service disconnect's amperage rating, if labeled; and
2. the type of wiring observed.

III. The inspector shall report as in need of correction:

1. deficiencies in the integrity of the service-entrance conductors insulation, drip loop, and vertical clearances from grade and roofs;
2. any unused circuit-breaker panel opening that was not filled;
3. the presence of solid conductor aluminum branch-circuit wiring, if readily visible;
4. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and
5. the absence of smoke and/or carbon monoxide detectors.

Cooling east**I. The inspector shall inspect:**

1. the cooling system, using normal operating controls.

II. The inspector shall describe:

1. the location of the thermostat for the cooling system; and
2. the cooling method.

III. The inspector shall report as in need of correction:

1. any cooling system that did not operate; and
2. if the cooling system was deemed inaccessible.

Cooling west**I. The inspector shall inspect:**

1. the cooling system, using normal operating controls.

II. The inspector shall describe:

1. the location of the thermostat for the cooling system; and
2. the cooling method.

III. The inspector shall report as in need of correction:

1. any cooling system that did not operate; and
2. if the cooling system was deemed inaccessible.

Attached Garage**The inspector shall inspect:**

garage vehicle doors and the operation of garage vehicle door openers, using normal operating controls.

The inspector shall describe:

a garage vehicle door as manually-operated or installed with a garage door opener.

Plumbing basement**I. The inspector shall inspect:**

1. the main water supply shut-off valve;
2. the main fuel supply shut-off valve;
3. the water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing;
4. interior water supply, including all fixtures and faucets, by running the water;
5. all toilets for proper operation by flushing;
6. all sinks, tubs and showers for functional drainage;
7. the drain, waste and vent system; and
8. drainage sump pumps with accessible floats.

II. The inspector shall describe:

1. whether the water supply is public or private based upon observed evidence;
2. the location of the main water supply shut-off valve;
3. the location of the main fuel supply shut-off valve;
4. the location of any observed fuel-storage system; and
5. the capacity of the water heating equipment, if labeled.

III. The inspector shall report as in need of correction:

1. deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously;
2. deficiencies in the installation of hot and cold water faucets;
3. active plumbing water leaks that were observed during the inspection; and
4. toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate.

Plumbing garage**I. The inspector shall inspect:**

1. the main water supply shut-off valve;
2. the main fuel supply shut-off valve;
3. the water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing;
4. interior water supply, including all fixtures and faucets, by running the water;
5. all toilets for proper operation by flushing;
6. all sinks, tubs and showers for functional drainage;
7. the drain, waste and vent system; and
8. drainage sump pumps with accessible floats.

II. The inspector shall describe:

1. whether the water supply is public or private based upon observed evidence;
2. the location of the main water supply shut-off valve;
3. the location of the main fuel supply shut-off valve;
4. the location of any observed fuel-storage system; and
5. the capacity of the water heating equipment, if labeled.

III. The inspector shall report as in need of correction:

1. deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously;
2. deficiencies in the installation of hot and cold water faucets;
3. active plumbing water leaks that were observed during the inspection; and
4. toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate.

Heating basement**I. The inspector shall inspect:**

1. the heating system, using normal operating controls.

II. The inspector shall describe:

1. the location of the thermostat for the heating system;
2. the energy source; and
3. the heating method.

III. The inspector shall report as in need of correction:

1. any heating system that did not operate; and
2. if the heating system was deemed inaccessible.

Heating**I. The inspector shall inspect:**

1. the heating system, using normal operating controls.

II. The inspector shall describe:

1. the location of the thermostat for the heating system;
2. the energy source; and
3. the heating method.

III. The inspector shall report as in need of correction:

1. any heating system that did not operate; and
2. if the heating system was deemed inaccessible.

Kitchen

The kitchen appliances are not included in the scope of a home inspection according to the Standards of Practice.

The inspector will out of courtesy only check:

the stove,
oven,
microwave, and
garbage disposer.

Laundry**The inspector shall inspect:**

mechanical exhaust systems in the kitchen, bathrooms and laundry area.

Attic, Insulation & Ventilation**The inspector shall inspect:**

insulation in unfinished spaces, including attics, crawlspaces and foundation areas;
ventilation of unfinished spaces, including attics, crawlspaces and foundation areas; and
mechanical exhaust systems in the kitchen, bathrooms and laundry area.

The inspector shall describe:

the type of insulation observed; and
the approximate average depth of insulation observed at the unfinished attic floor area or roof structure.

The inspector shall report as in need of correction:

the general absence of insulation or ventilation in unfinished spaces.

Interior Stairway**The inspector shall inspect:**

a representative number of doors and windows by opening and closing them;
floors, walls and ceilings; stairs, steps, landings, stairways and ramps;
railings, guards and handrails; and
garage vehicle doors and the operation of garage vehicle door openers, using normal operating controls.

The inspector shall describe:

a garage vehicle door as manually-operated or installed with a garage door opener.

The inspector shall report as in need of correction:

improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards and railings;
photo-electric safety sensors that did not operate properly; and
any window that was obviously fogged or displayed other evidence of broken seals.

Maintenance Items

Keeping up with maintenance items in a home is essential to prevent minor issues from becoming costly repairs. Regularly checking and servicing systems like HVAC, plumbing, and electrical ensures they operate efficiently and safely. Additionally, routine upkeep can enhance the home's value and provide a comfortable living environment for its occupants.