POWER WASH

Client: Spencer Stephenson

Unit #: 123 CLUBROOT DISINFECTION REPORT

Date: 1995-11-08

Tech: Liam Dave Kircher Liam David

UNIT NUMBER Supervisor: Spencer

DESCRIPETION 3

LOCATION 9.497682,-119.590669



The ure, encompassing several steps. This included a high-pressure hot water the rinse, and the application of a concentrated bleach solution. The bleach suspension, axles, and more. It's important to note that the bleach solution employed contained 6% sodium hypochlorite.

The checklist and accompanying images below serve as evidence that the disinfection process adhered to the specified standards and was executed accurately.

STEPS	CHECK WHEN COMPLETED Notes: The unit had a light coating of dust and grime and did not require in-depth pre-cleaning. HD equipment service.			
Step 1: Pre-wash Visual Inspection (note areas of dirt/debris accumulation)				
Step 2: Before Wash Photos	[X] Left Side	[X] Right Side	[X] Underside	[X] Wheel Well
Step 3: High Pressure, Hot Water Wash with detergent	[X] Exterior [X] Rims	[X] Underside [X] Tires	[X] Wheel Wells [X] Suspension	[X] Frame Rails
Step 4: High Pressure, Hot Water Rinse	[X] Exterior [X] Rims	[X] Underside [X] Tires	[X] Wheel Well [X] Suspension	[X] Frame Rails
Step 5: After Wash and Rinse Photos	[X] Left Side	[X] Right Side	[X] Underside	[X] Wheel Well
Step 6: Application of Clubroot Disinfectant	[X] Left Side	[X] Right Side	[X] Underside	[X] Wheel Well
Step 7: Disinfecting Photos/Video	[X] 2 Photos of Spraying Wheel Wells			