

CLUBROOT DISINFECTION REPORT

DATE		
UNIT NUMBER		
DESCRIPTION	5	
LOCATION		

The unit underwent a thorough disinfection procedure, encompassing several steps. This included a nign-pressure hot water wash with detergent, a high-pressure hot water rinse, and the application of a concentrated bleach solution. The bleach was evenly distributed across all parts of the vehicle's underside, including the tires, rims, wheel wells, frame, suspension, axles, and more. It's important to note that the bleach solution employed contained 6% sodium hypochlorite.

The checklist and accompanying images below serve as evidence that the disinfection process adhered to the specified standards and was executed accurately.

STEPS	CHECK WHEN COMPLETED			
Step 1: Pre-wash Visual Inspection (note areas of dirt/debris accumulation)	Notes: The unit had a light coating of dust and grime and did not require in-depth pre-cleaning. HD equipment service.			
Step 2: Before Wash Photos	[X] Left Side [X] Right S	ide [X] Underside [X] Wheel Well		
Step 3: High Pressure, Hot Water Wash with detergent	[X] Exterior [X] Undersi	[X] Suspension		
Step 4: High Pressure, Hot Water Rinse	[X] Exterior irchex Undersi			
Step 5: After Wash and Rinse Photos	[X] Left Side [X] Right Si	ide [X] Underside [X] Wheel Well		
Step 6: Application of Clubroot Disinfectant	[X] Left Side [X] Right S Spencer Stephenson	Side [X] Underside [X] Wheel Well		
Step 7: Disinfecting Photos/Video	[X] 2 Photos of Spraying Wheel Wells			



CLUBROOT DISINFECTION

BEFORE PICTURES		
LEFT SIDE	RIGHT SIDE	
WHEEL WELL	UNDERCARRIAGE	



CLUBROOT DISINFECTION

AFTER PICTURES				
LEFT SIDE	RIGHT SIDE			
WHEEL WELL	UNDERCARRIAGE			



CLUBROOT DISINFECTION

DISINFECTING PICTURES				
WHEEL WELL		UNDERCARRIAGE		
WORKER				
NAME (print)		SIGNATURE		
FOREMAN				
NAME (print)		SIGNATURE		