
RFID SCANNER

Design Document

Transition State Diagram and High Level Pseudocode

Rough initial design document for the Win32 RFID Scanner.

State Diagram



Pseudocode

WinMain: Create ConnectModeThread. WinMainThread: (Continuation on WinMain) WinGUI: Displays list of messages read. WndProc: Handles menu item being selected. Menu: **Settings:** Modify any settings if needed. Help: Brief explanation on how to use the program. **Connect/Disconnect:** Terminates and recreates the ConnectModeThread as needed. **ConnectModeThread:** Establishes a connection with the RFID. On successful connection: Read/Write loop: **Read:** Reads from the USB port connected to the RFID. On successful read: Send read info to WinGUI

```
Write: If a command is prepared to be sent, write to the USB port.

On Fail

terminate ConnectModeThread
display message saying "Failed To Connect."

Read/Write Loop:
while(1)
```

Read();

if (writeMessageAvailable)

Write(message)