PowerSDR keyboard shortcuts.

PowerSDR must be in **FOCUS** (Mouse Click somewhere on the PowerSDR console screen) for the PowerSDR to respond to keyboard input.

Function	Key	ALT	CTRL	ALT + CTRL	CTRL + SHIFT	Shift + ALT
Ke9ns: Mouse over a	Right					
PowerSDR button usually	mouse					
brings you to its SETUP	Click					
page						
OR						
Ke9ns: Mouse over a DX						
spot on Pan, opens QRZ						
page OR						
Ke9ns: Mouse over a SWL						
spot on Pan, opens Google						
page OR						
Ke9ns: Mouse over ID						
timer, toggles between						
voiceID, waterID, and Pop-						
Up						
Ke9ns: Show DX Spotters	SHIFT					
on Pan and Lat/Long on						
Pan (instead of DX Spots)						
Or						
With Mouse over Band						
Button causes dec in the						
BandStack.						
Or Deserts Detabase to Factory						
Resets Database to Factory Defaults if Held at Power						
UP.						
Ke9ns: When mouse over a	CTRL					
DX spot, sets VFOA, Mode,	CINE					
Split, and RX Filter to that						
DX Spot						
Change VFO Freq (by the	Mouse					
current Tune Step amount)	Wheel					
Change VFO Freq (by the	PowerMate					
current Alt Tune Step	Knob					
amount)						
-1 MHz	Α					
+ RX FILTER (F1-	В					
F10,VAR1/2)						
	С					
-10 KHz	D					
+10 KHz	E					
-1 KHz	F					
-100 Hz	G					
-10 Hz	Н					

- RIT				
-1 Hz	J			
Filter width inc (50hz)	K			
Filter width dec (50hz)	L			
+ BAND	M			
- BAND	N			
+ RIT	0			
- XIT	P			
+1 MHz	Q			
+1 KHz	R			
-100 KHz	S			
	T			
+100 Hz +1 Hz	U			
	V			
- RX FILTER (F1- F10,VAR1/2)				
+100 KHz	W			
+ MODE	Х			
+10 Hz	Υ			
- MODE	Z			
Automatically finishes an	ENTER			
"Accept" button	Enter Key			
operation(if the control				
features an Accept button)				
Or				
Whatever windows object				
has the current Focus				
Cancel button (if the	ESC			
control features a Cancel				
button)	Current Barr			
(LEFT) Mouse Click over	Space Bar			
the last selected control	Space			
(current Focused object)				
Allows direct VFOA	0.0 and an			
	0-9 and . or			
frequency Entry	,			
+ XIT	Г			
T //!!	L 1			
CM/ DOT /deasn't appear to	J			
CW DOT (doesn't appear to be hooked up)	•			
CW DASH (doesn't appear to be hooked up)	?			
Taggle MUT butters	* //			
Toggle MUT button	* (keypad only)+			
AF level inc	+ (keypad only)	 		
AF level dec	- (keypad			
7.1. 12761 466	only)			

F1			<u> </u>
'			
F2			+
			
ł			
l			
F9			
F10			
F11			
F12			
			CTRL SHIFT A
			CTRL SHIFT C
			CTRL SHIFT D
			02
+			CTRL SHIFT F
			CIKE SIM II
+			+
+			CTRL SHIFT I
			CIRLISHIFITI
-			
-			CTRL SHIFT O
			CIRL SHIFT O
 			CTDL CLUST D
			CTRL SHIFT P
-			CTDL CLUST D
			CTRL SHIFT R
 			OTRI CIUST C
			CTRL SHIFT S
			CTRL SHIFT T
			
			CTRL SHIFT V
		CTRL ALT A	
		CTRL ALT 4	
	l l		
		F2 F3 F4 F5 F6 F7 F8 F9 F10 F11	F2 F3 F4 F5 F6 F7 F8 F9 F10 F11 F12

RX2)					
·			CTDL ALT D		
Hidden: DSP test form			CTRL ALT D		
(WBIQ, Manual Notch, NR,					
ANF, DC Block)			0771 117 0		
Hidden: Flex-1500: TX			CTRL ALT G		
image calibration form					
Flex-5000 (RX2 only) ESC			CTRL ALT R		
(Enhanced Signal Clarity)					
FlexWire UCB config and			CTRL ALT U		
setup form (I^C bus)					
Hidden: Toggles Full			CTRL ALT F		
Duple x button on/off					
(button located just to left					
of words "Tune Step:")					
Change AGC-T level inc		CTRL +			
(see CTRL R)					
Change AGC-T level dec		CTRL -			
(see CTRL E)					
Change Tune Step Up		CTRL (left			
(larger step)		arrow)			
Change Tune Step Dwn		CTRL			
(smaller step)		(right			
(Sitialier Step)		arrow)			
Mausa Mhaali Frag ing (by					
Mouse Wheel: Freq inc (by		CTRL (up			
Tune Step amount)		arrow)			
Mouse Wheel: Freq dec (by		CTRL			
Tune Step amount)		(dwn			
		arrow)			
QuickSave current Freq		CTRL C			
(just below VFO LOCK					
button)					
Toggle between: Spectrum,		CTRL D			
and Panadapter modes					
Change AGC-T level dec		CTRL E			
Narrow current RX filter by		CTRL F			
5hz (see ALT F)				1	
Toggle VFO LOCK button		CTRL L			
Toggle MOX button		CTRL M			
Toggle ANF button		CTRL N			
Toggle PreAmp mode		CTRL P			
Change AGC-T level inc		CTRL R			
Toggle SPLIT button		CTRL S			
Toggle RESTORE button		CTRL V			
(QuickSave restore)					
CW speed value dec		CTRL W			
(see ALT Q)		CINEVV			
Ke9ns: WORLD MAP		CTRL Z			
Mic level inc	AIT /	CINLZ			
iviic ievei iiic	ALT (up				
Mic level dec	arrow)				
Mic level dec	ALT (dwn	<u> </u>			

	arrow)		
Vox level inc	ALT (left		
VOXICVELITIE	arrow)		
Vox level dec	ALT (right		
VOX IEVEL GEC	arrow)		
Drive level inc	ALT +		
Drive level dec	ALT -		
Widen current RX filter by	ALT F		
5hz (see CTRL F)	ALIT		
VFO A > B button	ALT G		
VFO B > A button	ALT H		
RX Filter Shift Reset button	ALT I		
Ke9ns: Add new Memory	ALT M		
directly from current	ALTIVI		
Panadapter			
Toggle NB2 button	ALT N		
	ALT Q		
CW speed value inc (see CTRL W)	ALIQ		
RIT Reset buton	ALT R		
	ALTT		
Toggle TUN button VFO A<>B button	ALT V		
XIT Reset button	ALT Y ALT Z		
Zero Beat button	ALI Z		
Catura Marila and a DTME			
Setup->Keyboard->DTMF			
OR directly from keyboard			
DTMF Tone 1	ALT 1		
DTMF Tone 2	ALT 2		
DTMF Tone 3	ALT 3		
DTMF Tone 4	ALT 4		
DTMF Tone 5	ALT 5		
DTMF Tone 6	ALT 6		
DTMF Tone 7	ALT 7		
DTMF Tone 8	ALT 8		
DTMF Tone 9	ALT 9		
DTMF Tone 0	ALT 0		
DTMF Tone *			ALT SHIFT 8
DTMF Tone #			ALT SHIFT 3
Hidden: Setup "PA		CTRL ALT A	
Settings" calibrate screen			
visible			
Hidden: Setup Signal		CTRL ALT O	
Generator TX Output			
visible			