

Incident Report 2

Pump trip caused production loss. Root cause under investigation.