

Inspection Report 1

Leakage observed on V-102. Recommend packing replacement.