

Inspection Report 2

Leakage observed on V-102. Recommend packing replacement.