

Inspection Report 3

Leakage observed on V-102. Recommend packing replacement.