

Inspection Report 4

Leakage observed on V-102. Recommend packing replacement.