

Inspection Report 5

Leakage observed on V-102. Recommend packing replacement.