

RCA Report 1

Bearing wear due to contamination from valve leakage.