

RCA Report 2

Bearing wear due to contamination from valve leakage.