

RCA Report 3

Bearing wear due to contamination from valve leakage.