

RCA Report 4

Bearing wear due to contamination from valve leakage.