

RCA Report 5

Bearing wear due to contamination from valve leakage.