

Safety Audit 2

Delayed repair of V-102 identified. Medium risk.