

Safety Audit 3

Delayed repair of V-102 identified. Medium risk.