

Safety Audit 4

Delayed repair of V-102 identified. Medium risk.